

VOLUNTARY SAFETY RECALL NOTICE

COSORI® Air Fryers (Models 158, 137, and 258)

Affected model numbers:

CP158-AF	CS158-AF
CP158-AF-R19	CS158-AF-RXB
CP158-AF-RXW	CS158-AF-R19
CP158-AF-RXR	CAF-P581S-BUSR
CAF-P581-BUSR	CAF-P581S-RUSR
CAF-P581-AUSR	CAF-P581S-AUSR
CAF-P581-RUSR	CO137-AF
CP137-AF	CO158-AF
CP137-AF-RXB	CO158-AF-RXB
CP137-AF-RXR	CO258-AF
CP137-AF-RXW	



HAZARD: The wire connectors in the affected air fryers can overheat, posing fire and burn risks.

REMEDY: Stop using your air fryer immediately. Receive a replacement air fryer (or you can choose from a selection of other COSORI products, depending on the model of your air fryer and subject to availability), at no additional cost by:

1. Registering online at www.recall.cosori.com, OR
2. Calling COSORI at 1-888-216-5974 (Monday through Friday, from 8:00 a.m. to 5:00 p.m. EST), OR
3. Scanning this QR Code:



Post by February 23, 2023, and until June 22, 2023

COSORI®